



Awake Flex Connector Maintenance



1. Rinse all gear with fresh water
2. Clean out any debris with a small brush
3. Wipe the connectors with IPA wipes
4. Grease connector O-rings with Super Lube grease

Battery connector



Connector sockets

CM connector



Connector pins

O-rings